DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-023344 Address: 333 Burma Road **Date Inspected:** 15-Jun-2009

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes N/A No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: OBG** Trial Assembly

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, S. Manjunath Math was present during the time noted above for observations relative to the work being performed.

This QA Inspector randomly observed the following work in progress:

Orthotropic Box Girder (OBG) Trial Assembly Areas

3AW and 3BW

This Quality Assurance (QA) Inspector witnessed final tension verification for Lower Chevron Brace at Counter Weight for Segment 3AW to 3BW between PP 19 to PP 23. Inspected 10% of bolt final tensioning found satisfactory. Bolt sizes used are M22-2.5x70 RC Lot No. DHGM220020 and final Torque required is 520 N-m; Bolt sizes used are M22-2.5x75 RC Lot No. DHGM220005 and DHGM220034 and final Torque required is 473 N-m and 453 N-m, but all the bolts torque verification carried out at 473 N-m. Manual Torque wrench is been used with Sr. No. X02-584. The Inspection was scheduled from 0810 Hrs.

3AW and 3BW

This Quality Assurance (QA) Inspector witnessed final tension verification for Floor Beam to I- Beam for Segment 3AW to 3BW between PP 19 to PP 23. Inspected 10% of bolt final tensioning found satisfactory for Counter weight and Cross Beam side. Bolt sizes used are M22 x 80 RC Lot No. DHGM220012 and

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

DHGM220050 final Torque required are 427 N-m and 486 N-m, but all the bolts torque verification carried out at 486 N-m. Manual Torque wrench is been used with Sr. No. X02-584. The Inspection was scheduled from 1000 Hrs.

3AW and 3BW

This Quality Assurance (QA) Inspector witnessed final tension verification for Side Panel Splice plate for 3AW to 3BW from PP 19 to PP 23 cross beam side. Inspected 10% found satisfactory. Bolt sizes used are M22x 2.5 x 65 RC Lot No. DHGM220021 and final Torque required is 543 N-m. The Inspection was scheduled from 1330 Hrs. 4AW and 4BW+ 3AW and 3BW

This Quality Assurance (QA) Inspector signed off the green tag document for 4AW to 4BW and 3AW and 3BW.

- 1.U-Rib to U-Rib for 4AW+ 4BW PP 24 and 25 Green Tag No. 43
- 2.Lower Chevron Brace (North and South) for 4AW and 4BW PP24-28 Green Tag No. 44
- 3.Lower Chevron Brace (North and South) for 4AW and 4BW PP24-28 Green Tag No. 45
- 4.FB to BP Clips for 3AW + 3BW PP19-23 Green Tag No. 48
- 5.FB to BP Clips for 3AW + 3BW PP19-23 Green Tag No. 49

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Math, Manjunath	Quality Assurance Inspector
Reviewed By:	Miller,Mark	QA Reviewer